Part No.		CY90001		Component		Ι Δ	A02002-0024					-
Order No. Order Qty		399843 400		Heat Lot #			A02002-0024			Parts (18)		
				_	W/O # from Box				Parts	912		
AND				OPERATION	# from Box ON 1		F12 75-38-01			TUDIL	NIT/OUDC	411
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time		Notes	THRU-P	Scrap	Scrap
CNC COBRA	3/2/16	BA	2,5	28	280	3	3				0	Code
Setup Hrs.	2.2.11	70	1.5	785	126		-	1	Marit J		0	
	3.3.16	BA	1	55	136	-		00	Jevo		0	
2,0	3/4/16	135	8	85	266	<u> </u>			Hy		6	
Cycle Time	3-4-16	RM	8	6.5	331			 			8	
Buin	315/16	BT	6	62	293						6	
4sec	3/5/16	57	.75	14	407						0	
Pcs/Hr	*				1							
AR												
ROUTING:												
Name I N				OPERATIO		Down			AT SPORTS	THRU-PI	UT/8HRS	
Mach No.	Date 3-2-16	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	time	Down time code		Notes		Scrap	Scrap Code
COPINA	3.2.16	R4	6.5	50	56	2,0		Sedyp	and a	PP P	0	
Setup Hrs.	3/3/16	57	5	50	109			1		1	0	
	344						1	D \0	-00		0	
0	35.16	BA	4	41	150				ly	- 8	0	
Cycle Time	3/7/16	BT	8	83	233			F/	Vy		0	
3 m	3/7/14	MC.	7	98	33)	0				_	0	
	3-7-16	550	94.5	55	392	1			110		0	
Pcs/Hr	3/8/16	135	\$1	10	400			1)	14			
17	3/2/10	15	7	2	, , ,			300	3.9.		0	
ROUTING:										_	0	
ROUTING:	· · · · · · · · · · · · · · · · · · ·	1000 B M C 21	550 176310	OPERATIO	N 3	12714						
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
				4								
Setup Hrs.												
Cycle Time												
Pcs/Hr		2						-	15			
ROUTING:												
Notes / In:	structions	Down Tir	ne Codes			Fi	irst Part Ins	pection F	lecord	3000		
1			Maintenance		Time Of Day	Approved	Mtrl	Rev		westere.		
2		Tooling Setup		Jubilitteu	7	Yes / No	Check	Letter	Inspector	Notes		
4		FAIR		3-1-16	6 pm	7	7		1C			
7	5 6	Training Meeting						-				
CONDARY	PRODUCTION				PAGE 1						Test Form 10	