Part No.		103147-1		Component		100046-999			control devices, Luc			
Order No.		391001		Heat Lot #					devices, LAC			
Order Qty		30		W/O # from Box								
司管理等等以及				OPERATION 1		建国际的专业区域		THRU-PUT/8HRS				
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
CNC T42	11-20-15	20	4.0	31	3/	1.0	3	Setup	\$ for _	B.	0	
Setup Hrs.	11.20.15	BA	8.0	19	21	113	3	SCT	ID ISTOP			
2.5	11/2/115	BT	5.5	10	3(*
Cycle Time	11/21/11	-9C.NG	7			15	3					
Cycle Time	11/23/15	BJ	6.5	12	12	15	3					
	11 23 18	T	5,0	10	22	2,0		Chorie	curtoff 1	ed e		
Pcs/Hr	11.23.15	BA	5,0	9	31	0,10		CI PIGC	And pro	erry		
		0.1										
ROUTING:		•		•								
				OPERATIO	NACY AND SALE		THRU-PUT/8HRS					
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
CNC T42	11/24/15	130	2.5	10	31	1,0	3					31.00
Setup Hrs.					7						15	
											117	
				211.0		<u> </u>				14	5	11
Cycle Time								h		+	5.	
											1	
									1			
Pcs/Hr							(M)			
											N	
DOUTING											X	
ROUTING:			罗 斯性 炒 旅	OPERATIO	N 3			a Stay 5		THRU-	PUT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes		Scrap	Scrap Code	
CNC- T42												
Setup Hrs.		5)										
											5.	
Cycle Time												
Pcs/Hr												
ROUTING:										-		
Notes / Instructions Down Time Codes First Part Inspection Record												
		1 Maintenance2 Tooling		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev Letter	Inspector Notes			
		3 Setup 4 FAIR										
		5 Training										
SECONDARY	/ PRODUCTIO	6 Meeting			PAGE 1						Tost Form	10/15/15