BRAZING PRODUCTION RECORD				Special	ROUTING:								3/8	Date			Caps,	Snap	Flare	Copper	Brazin	Flare		Orde	Orde	
TOTION DECO				Special Notes / Instructions									SB	Emp. Name	Mach. No.		Caps/Plugs	Snap Rings	Flare Tubes	Copper Tubing	Brazing Rings	Flare Nuts		Order Qty	Order No.	
	6	ω 4 ι	2 1	ctions										Prod Hrs.			Do not requ	Located on	Use their w	Located on	Located on	Six digit no.	Disting		39	
	Training Meeting			Down Time Codes					1				و	Total Pcs.		Designation is not the	Do not require traceability.	Located on the bag followed by "Lot Number."	Use their work order number and date on the box label.	Located on the spool label, starting with the letter "M."	Located on the box label, directly above the word "heat."	Six digit no. located on the box label under box quantity.	Distinguishing Traceablity Numbers	12	399749	
				Codes										Cum	Hrs.	Setup	ŢŸ.	ved by "Lc	nber and c	el, starting	, directly a	ne box lab	blity Num			L
			Date Part Submitted											Cum. Total				t Number	date on the	with the	bove the	el under b	bers		1	
			Time Of Day											Down Time	Time	Cycle			e box label.	letter "M."	word "heat.'	ox quantity.			devices, LLC	223733
			Approved Yes / No											Down Time Code		NATION CONTROL									LLC	
		Mtrl R	T												A COMPANIES		U									
				First Part In											Pcs./Hr	Salah Sanda			g						Con)
			Inspector	Inspection Record										Notes						1			J-RING	J1/2	Component(s)	
							7	1X4							put/8hrs	1							301			ווכמנוני
			Notes				Q.	(0								S						20140766	NA	No(s)	medicach ligged billity
					Ċ	P								Scrap												1
										×				Scrap												