Part No. Order No.	1103-2 <b>39</b> 2	393389		A	control devices, LLC	LLC		Com	Component(s)	Heat Lo	Heat Lot/Traceability No(s)
Order Qty								110	1103-21-1/4		Z/A
	Distingu	Distinguishing Traceablity Numbers	lity Numb	ers					C25	7	N/A
Flare Nuts	Six digit no.	Six digit no. located on the box label under box quantity.	box labe	l under bo	ox quantity.			_	C-RING		ZA
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	directly ak	ove the v	vord "heat."					*	
04	Located on	Located on the spool label, starting with the letter "M."	, starting	with the l	etter "M."						
	Use their w	Use their work order number and date on the box label	ber and d	ate on the	box label.						
	Located on	Located on the bag followed by "Lot Number."	ed by "Lo:	t Number	- =						
	Do not requ	Do not require traceability.	6								
			· 1000000000000000000000000000000000000						Market Salving States	SAN SHARM SHARMS	
Mach. No.			Setup Hrs.		Cycle Time			Pcs./Hr		Thru- put/8hrs	
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum.	Cum. Total	Down Time	Down Time Code			Notes		
12/10 58		E									$\rfloor$
									73	5,	
ROUTING:									,		
Special Notes / Instructions	ctions	Down Time (	Codes					irst Part In	First Part Inspection Record		
		<ol> <li>Maintenance</li> <li>Tooling</li> </ol>		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev Letter	Inspector		Notes
		4 FAIR 5 Training									