PRODUCTION RECORD Order No. Order Qty control devices, LLC 02/24 02/29 Part No. 2/24 Date CUMULATIVE TOTAL FROM PREV. PAGE 120 PWN 40037 100 Emp. Name 50 60 000 J. 40188 FOR DAVENPORTS & BROWN & SHARPES ONLY: To Figure Pieces From Loads = Pcs/Bar x Total loads ran during shift x Bars per load Prod. Hours 0 TOTAL PCS. PRODUCED 0 3 75 0 IS 1368 Total Pcs 0 Special Notes / Instructions 6 Standard Actual Cum. Total 6 3 0 00 26260 Planned Pcs/Hr Material Heat Lot No. Actual Pcs/Hr Thru-Put/8Hrs First Part Inspection 0 Record Date Part Submitted Down Time N Component Wgt/Bar Wgt/Pc. N 5 Time Code N 2 Time of Day 10:15 WRAD. FAIR TOTAL SCRAP PCS. FROM PREV. PAGE Approved Yes/No NO Check Mtrl Notes 5 Letter Rev - Maintenance
- Tooling
- Setup
- FAIR
- Training
- Meeting 5 0 Inspector TOTAL SCRAP PCS. Montes 09 09 ar Setup Allowed Hrs. Pcs./Bar Mach No. Notes Scrap Pcs. 0 Test For 8 Ō 10 S Scrap Code C O