Part No.		M4-4-3		Cor	mponent	A02071-0026			CD control devices				
Order No.		389815		He	eat Lot#	1	190167.1.1			devices			
Ord	ler Qty	2.	500		# from Box								
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down	Down time code		Notes	THRU	Scrap	Scrap Code	
C2	11-9-15	JB	3.5	188	188	2.5	3				0	code	
Setup Hrs.	11-10-15 N-11-15	JB JR	8,5	418	1156						0		
	11-12-15	JB	8	200	1656						0		
2.5	11-13-15	JB	7	393	1056			lak	n +	El5	0		
Cycle Time				515		<u> </u>		Jol	100 C	را ل	U		
618								35					
Pcs/Hr								22	SP				
47								Not	65		0		
ROUTING:					///VCH / C/	 ANDBLAST /	DACK	11	1				
KOOTING.				OPERATIO		ANDBLAST /	PACK		CT AND SOME	THRU	-PUT/8HRS		
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code	
<u> </u>													
Setup Hrs.													
											1		
Cycle Time													
_													
Pcs/Hr													
PCS/HI					-						(2) (2)		
										b	**		
ROUTING:	N-E												
MICHEL PROPERTY.	PROPERTY.			OPERATIO	N 3	ACCESS OF		KALES S	艾斯尼 斯	THRU-	PUT/8HRS		
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes			Scrap	Scrap Code	
Setup Hrs.			,		HE .								
Cycle Time													
-									311				
Pcs/Hr			escare.					1					
					_	7.							
ROUTING:				560		r.							
	structions	Down Ti	me Codes			Fi	rst Part Ins	spection R	ecord				
i i		1 Maintenance 2 Tooling		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev	nspector		Notes		
		3 Setup 4 FAIR		N-10-14	8:45	45/		A	DITTO	80# 801 MD			
		5 Training 6 Meeting											
ECONDARY	PRODUCTION		_		PAGE 1						Test Form 1	0/15/15	

PRODUCTION WORK ORDER

Run

Setup

Inspect

Order-No Byr Loc Item-No	======= Description	Down
389815 K1 MS M4-4-3	Order-Qty DISTRIBUTOR, VENTURI, SPECIAL 2,500.0000	Unit-Cost Start-Dte Due-Dte
Primary Work Cell: CNC Lev Seq Loc Item-No. 1 1 MS A02071 0005	Customer: Ref: Sales-Order-No: Description Qty Nee	.000000 .375400 11/05/15 11/09/15 Job No: Parent Order No:
1 MS A02071-0026 1 2 MS SC-1015	SRA W/O MN TEST 550.0000 SCRAP - BRASS	Uty-Used Picking Seq
	300.0000	LB

uction-Notes:		
roduced-By:	Date	
	Date:	

CNC IN-PROCESS INSPECTION RECORD

PART NO. M4-4-3

REV.__A__

Mach. No C2

DATE/TIME	DIM#	1 DIM #	2 DIM #	3 DIM #4	DIM #	E D'11- 11			0111 0	rder 38	1013			
	.813 dia	a. 1.24 OA		.310	1		6 DIM #	7 DIM #	8 DIM #9	DIM #10	DIM #11	T		
		1			.235 dia	1. 14° x 1	.254 dia	a170 dia	.250	.010 OD	14° x 3 hole	DIM #12	DIM #13	I
11/10		+/010	+/002	+/010	+/003				1	break	angle	Hole	No Step @	1
7	Saugura	ANTES CONTROLLED	actions:		x 1	BEGINS	Unit of the second	1000	+/010		per print	spacing por	Bore/Blend radius/ Per	Y
		-	+			1000000	x3	x 3	x 3			print Note #5	print	1
18m 2	312	1222					-	-			19 199,0101	经社会的自由的政治		
11-11-15) lot	1237	.475	1315	ale	140	023							L
6:10Au	Oin	122/				14	00	Q1 3	24743	1	140		44	L
11-11-15	217	1.236	.429	1315	at ,234	140	208					074.140	a	On
12:400	012	1 - 5	-			1/	,253x3	ok3	,242	OK	OK	NC LINA	-,-	,
12:40 pm g	017	1.232	14295	1316	,234	1/	0.50	+			02	065/137	ok	ck
						/	:253	OK	,236	ok	OF A	Nillan	-	,
6:05A-18	12	1.235	,429	.315	.234	1/	207			1	Or a	064/134	ok	2k
6;10Am, 8	217	1220				/	1253	et	,236	X	ck .	011/20	-/-	
10. JAM 10	1 4	1, 722	1429	1316	234	1/	200	-/-				06/138	of	3/0
					22/	V	1253	ok.	236	OK	ak 1	11/10	-,	
	-										62 K PL	66/:138	ok c	3/
	-													
			- C C C C C C C C											_
	-													
ATE/TIME	41537.EEF5000													
	Large M				THE STATE	MARKET FROM	Zonadanski nes	PARTIES CO.						
	+-									HEE SA	Headstand	Cover Days		
	+-								1.00		SWIELD FOR STANKING			
	+-								A					
	+					-	-							
	-						3							
	_				100							_		
	+-													
	+-					-	_					-		
7	-					-								
-	+				\neg		-				_			
	-					-	_					-		
	-											_		
					_	-+-	-				_	-		
-		-									-			
						+	_			_	-	-		
-) }				-	-				+				
					-	+	-				-			
S:						M		1 2 2 5 5 1		+				
1.00 to 1.00 to						N.								
											-			_
														_



