Part No. Order No.		SB5050-10 394407		Component Heat Lot #		\$B5050-20			. 1	GI	contro	ol lo
									5			
Ord	er Qty	2	50		from Box			A ROULES	V	TUDU	DUT/OUDC	
Mach No.	Date	Emp. Name	Prod Hrs.	OPERATIO	Cum. Total	Down	Down time code		Notes	THKU	PUT/8HRS Scrap	Scrap Code
HARDING	12/21/15	IT	.4	6		- tille	"				3	- /1
LATHE0467	12-22-15	12.6	N.	150	153						/ ,	
Setup Hrs	12-22-15	66		74	227			λ		,	15	1
.2	12/21/15	ゴナ	1.3	289	295			1		-	3,7	And .
Cycle Time								1		1	alle	00
								_ \		-	m. M	
Pcs/Hr			^	W.				3	_/\			
		1		00								
DOUTING:			\									
ROUTING:				OPERATIO	N 2					THRU-	PUT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
Setup Hrs.						-						_
Cycle Time			- 11100211					- <del> </del>				
									_			
2 (1)												
Pcs/Hr												
ROUTING:	11回接发 C 表现 <del>有用</del>	SWINSWILL		OREDATIO	N a						DUT/QUES	
Mach No.	Date	Emp. Name	Prod Hrs.	OPERATION 3  Total Pcs. Cum. Total		Down	Down time		Notes THRU-		PUT/8HRS Scrap	Scrap
Wideli No.	Dute	Linp. Name	TTOG TITS.	Total res.	Cum. Total	time	code		Notes		эсгар	Code
					<u> </u>							
Setup Hrs.												
Cycle Time												
									-			
Pcs/Hr									2			
ROUTING:												
	nstructions	Down T	ime Codes			F	irst Part In	spection	Record	1		
		<ol> <li>Maintenance</li> <li>Tooling</li> </ol>		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev Letter	Inspector	Notes		
		3 Setup		12-21-15	12:30 pm	yE)	CHECK	D	DH	Adomi MADICE		
		5 Training				/						(09)
SECONDARY	Y PRODUCTIO	6 Meeting N RECORD			PAGE :	1					Test Form	10/15/15