## " Quality Alert "

ID #: QA-029

Part #: IF5050B24


## **Problem Description:**

Sealing surface cut/knicked when side holes were machined.

## **Containment Action:**

100% visual inspect all parts coming off of machine

BAD BAD





**Department Mgr: Ken McGuire** 

**Quality Engineer: Matthew King** 

**Quality Director: Dave Besancenez** 

**Team Fact. Signature:** 

Removal Date: End of run - Keep with Master file

**Distribution: CNC Department**