PRIMARY PRODUCTION RECORD PAGE 1 2-5-5 Order No. Order Qty control devices, LLC Part No. 12 12/9 Date 9 Emp. Name 20XXXX MA 0000 0 FOR DAVENPORTS & BROWN & SHARPES ONLY: To Figure Pieces
From Loads = Pcs/Bar x Total loads ran during shift x Bars per load Leve Prod. Hours OR DE TOTAL PCS. PRODUCED 3 1.500 240 900 Total Pcs 450 241 OAS Special Notes / Instructions Standard Actual 7690 3250 0190 Srs Cum. Total 7 P9315 Planned Pcs/Hr Material Heat Lot No. Thru-Put/8Hrs Actual Pcs/Hr 1250340 First Part Inspection 0 Record Date Part Submitted Down Component Wgt/Pc. Wgt/Bar Time Code Time of Day 10 Approved Yes/No Check Mtr Notes Letter - Maintenance
2 - Tooling
3 - Setup
4 - FAIR
5 - Training
6 - Meeting Rev Inspector TOTAL SCRAP PCS Setup Allowed Hrs. Pcs./Bar Notes Mach No. Scrap Pcs. Code Scrap