BRAZING PRODUCTION RECORD		Special No	ROUTING:		9118K	Date Er	2	Caps/Plugs	Snap Rings	Flare Tubes	Copper Tubing	Flare Nuts		Order Qty	Order No.	Part No.
CTION RECOR		Special Notes / Instructions			S	Emp. Name	Mach. No.							Ωty	Vo.	
ס	654321	ons			the 5	Prod Hrs.		o not requi	ocated on t	se their wo	ocated on t	ix digit no. I	Distingui		403	4T-0-C-4C
	Maintenance Tooling Setup FAIR Training Meeting	Down Time Codes			0	Total Pcs.		Do not require traceability.	Located on the bag followed by "Lot Number."	rk order num	he spool labe	located on the	Distinguishing Traceablity Numbers	10	403426	1
	Subn	odes			/0	Cum. Total	Setup Hrs.	<i>\</i> .	ed by "Lot Nu	ber and date	l, starting wit	e box label un	olity Numbers		1	
	Date Part Submitted  SS-/6  10:45					al Down Time	Cycle Time		mber."	Use their work order number and date on the box label.	Located on the spool label, starting with the letter "M."	Six digit no. located on the box label under box quantity.	n		devices, LLC	ı
	Approved Yes / No					me Down Time Code				el.	at."	ity.			S, LLC	-
	Mtrl Rev Letter	First Pa					Pcs./Hr					I		ſ		
	ter Inspector	art Inspection Record		7		Notes	Ĥ			CP13	BRZ01	CUTU-14-3/16	CUTU-3-1/2	SF4-3-8	Component(s)	
		rd		1		S.	Thru- put/8hrs				<u> </u>	2,				I I Heat Lo
	Notes					Sc							A	A/	No(s)	Heat Lot/Traceability
			X			Scrap	ong age			_1_						-
L		4				Scrap Code										