Heat Lot # W/O # From Box Series Notes Notes Series Notes Series Notes Series Notes Series Notes N	THE PARTY OF THE P												
Order City Setup Hrs. Order			401483		Heat Lot # W/O # from Box		5	502-A-BLNK			control		
Date												device	es, LL
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down Code Code													
Setup Hrs. 10 MIN Pes/Hr 18 ROUTING: OPERATIONS THRU-PUT/BHRS Scrap Cod Setup Hrs. DOERNOONS THRU-PUT/BHRS Scrap Sc					OPERATIO	DN 1	24 550 200			ME STEELS IN	THRU-PU	T/8HRS	
Setup Hrs. 10 MIN Pcycle Time ROUTING: OPERATION:	Mach No.			Prod Hrs.	Total Pcs.	Cum. Total				Notes		Scrap	Scrap Code
10 MIN	80	2-22-16	CS	1.75	e	11			5	. (1	1	1	H
10 MIN								101	5-	DU!			<u> </u>
Cycle Time													
3 MIN	Anne de la companya	-								1) 110		
Pes/Hr									1	0	10		
ROUTING:									7	000	2		
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down fire Code					_					-			
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total												İ	_
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Cum.	ROUTING:		of a fill the years	5-18-27 (2)	OPERATIO	N 2	Marie Carlo	of (free same			THRILDII	т/опрс	
Setup Hrs. Set	Mach No.	Date	Emp. Name	Prod Hrs			Down			Notes			Scrap
Cycle Time				71001113.	Total Tes.	Cum. Total	time	code		Notes	•	scrap	Code
Cycle Time	Satur Hrs				22								
Pcs/Hr	Setup IIIs.												
Pcs/Hr													
ROUTING: Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down time code Notes Scrap Code	Cycle Time						_			_			
ROUTING: Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down time code Notes Scrap Code													
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down time code Notes Scrap Code	Pcs/Hr												
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down time code Notes Scrap Scrap Code										112			
Mach No. Date Emp. Name Prod Hrs. Total Pcs. Cum. Total Down time code Notes Scrap Scrap Code	ROUTING:												
Setup Hrs. Set	BOLD BUT		A PASSAN	A DOMESTIC		N 3	Day 1				THRU-PUT	/8HRS	
Cycle Time	Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	26			Notes	S	crap	Scrap Code
Cycle Time	Satur Hrs												
Pcs/Hr	setup Hrs.												
Pcs/Hr													
ROUTING: Notes / Instructions Down Time Codes I Maintenance 2 Tooling 3 Setup 4 FAIR 5 Training 6 Meeting Down Time Codes Date Part Submitted Time Of Day Yes / No Check Letter Time Of Day Yes / No Check Le	Cycle Time												
ROUTING: Notes / Instructions Down Time Codes I Maintenance 2 Tooling 3 Setup 4 FAIR 5 Training 6 Meeting Down Time Codes First Part Inspection Record Approved Mtrl Rev Letter Ves / No Check Letter Inspector Notes Notes		New York							4				
Notes / Instructions Down Time Codes I Maintenance 2 Tooling 3 Setup 4 FAIR 5 Training 6 Meeting Date Part Submitted Time Of Day Yes / No Check Che	Pcs/Hr												
Notes / Instructions Down Time Codes I Maintenance 2 Tooling 3 Setup 4 FAIR 5 Training 6 Meeting Date Part Submitted Time Of Day Yes / No Check Che											-		
1 Maintenance 2 Tooling 3 Setup 4 FAIR 5 Training 6 Meeting													-
2 Tooling Submitted Time Of Day Yes / No Check Letter Inspector Notes 3 Setup 4 FAIR 5 Training Meeting Meeting	Notes / In	structions		The second second			F	irst Part In	pection	Record			
3 Setup 4 FAIR 5 Training 6 Meeting						Time Of Day		114 - 1		Inspector	Notes		
5 Training 6 Meeting			and the state of t		Submitted		Yes / No	Check	Letter				
6 Meeting			4 FAIR										
												-11-	
ECONDARY PRODUCTION RECORD PAGE 1 Test Form 10/15/15	ECONDARY			-		DACE 1							