Part No.	706-1	706-15-1/4-25			ontrol				non-1/-1	Heat Lot/	Heat Lot/Traceability		
Order No.	39	392873		H	devices, LLC	LLC		COLL	component(s)	7	No(s)		
Order Qty		2						70	706-15-1/4	Z/A	A		
	Distingu	Distinguishing Traceablity Numbers	lity Numb	ers					G25	N/A	A		
Flare Nuts	Six digit no.	Six digit no. located on the box label under box quantity.	box label	l under bo	ox quantity.				G-RING	301	30151504		
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	directly ab	ove the v	vord "heat."								
Copper Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting	with the l	etter "M."								
Flare Tubes	Use their w	Use their work order number and date on the box label	er and da	ate on the	box label.								
Snap Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lot	: Number.									
Caps/Plugs	Do not requ	Do not require traceability.											
	A SALL TRANSPORT								Charles Land and Secretary		Street Shipperson		を対し
Mach. No.			Setup Hrs.		Cycle Time			Pcs./Hr		Thru- put/8hrs			
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Total	Down Time	Down Time Code			Notes		Scrap	-	Scrap
12/7 58		ىو											
ROUTING:													
Special Notes / Instructions	ıctions	Down Time Codes	odes				F	irst Part In	First Part Inspection Record				
		 Maintenance Tooling 		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl	Rev Letter	Inspector		Notes		
	15.		_										
		6 Meeting											_
BRAZING PRODUCTION RECORD	ORD											Test Form 11/4/15	11/4/15