Part No. Order No.		FS128 384871		Component Heat Lot #		A02001-0016			CD control devices, LLC		
									1		
Orde	er Qty	10	100 500 f	W/0#	from Box	2014	ni suri basa S				
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	OPERATION Cum. Total	Down time	Down time code		Notes	Scrap	Scrap Code
CNC HARDING	11-9-15	11.5	5.5	40	41	4.5	3			6	T4
Setup Hrs.	11.10.15	30	6.0	58	99						
4	11-10-15	BH	8:0	87	186	.5	6				
Cycle Time	11/11/15	30	8.0	135	376	• 7	6	. 11) /		
3MIN 11 SEC	W. M. 15	BA	5,0	58	434			V	40:00	0	
Pcs/Hr	11/2/16	00	3.0	4	527				A 1/2	37-	
r CS/ FII	11/10/15		5,0	7.0		1	1			7	
15		\			1	be	1/1		Approx	10	
ROUTING:					PA	CK DEPT	10 1			10	
			SOURCE OF STREET		OPERATIO			A NOTE			
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes	Scrap	Scrap Code
Setup Hrs.	200012										
Cycle Time											
Pcs/Hr											
			- 11 - 11V								
ROUTING:											
Meeting:					OPERATIO	DN 3		I WARK			S. (1)
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes		Scrap	Scrap Code
Setup Hrs.											
Cycle Time								-:			
Pcs/Hr											
ROUTING:	structions	Down T	ime Codos			-	iret Boet I	enect!	Doccard		
Notes / Instructions FOR B&S ONLY: To Figure		Down Time Codes 1 Maintenance		Date Part	Date Part To Of D App		First Part Inspection Mtrl Rev			200 - 17	
Pieces From Loads = Pcs/Bar x		2 Tooling		Submitted	Time Of Day	Approved Yes / No	Check	Letter	Inspector Notes		
		3 Setup 4 FAIR		11/10	1230Am	gas			Mh		
wis her loan		4 FAIR 5 Training				0		Α			
	PRODUCTIO	6 Meeting			PAGE					9)	