Part No.		11-4-26			Com	ponent	11-4-L-BLNK			control devices, LC			
Order No.		388324			Hea	at Lot#					<b>611</b> &	gevice	s. LLC
Order Qty		8				from Box	388178						
		CI HARDEN TO		0	PERATIO	N 1			S PRAMILE		PUT/8HRS	Covon	
Mach No.	Date	Emp. Name	Prod Hrs.	T	otal Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
10	11/5/15	DG	5			10			50	013		-	
Setup Hrs.									$\mathcal{O}$	UT		<u> </u>	
8 min	(									()			
Cycle Time										/			
55sa.								<i>x</i>	11	1/5			
Pcs/Hr									11	50			
0									\	<u> </u>		X	
ROUTING:	- 1											,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	4323	ACCESSED TO A STOLE			PERATIO	N 2		THE STATE OF	THRU			PUT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	T	otal Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
												1	
Setup Hrs.	Ų.												
												•	
Cycle Time													
Pcs/Hr													
			_			_							
										- K			
ROUTING:													***
Mach No.	Date	Date Emp. Name Pr			PERATIO otal Pcs.	N 3 Cum. Total	Down	Down time code	Notes		THRU-	PUT/8HRS Scrap	Scrap Code
			_				time	5950-5557.					code
Setup Hrs.				_						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
				$\vdash$					211000				
Cycle Time												ε	
	100												
Des // )::													
Pcs/Hr													
ROUTING:	ROUTING:												
	nstructions	Down T	ime Codes				F	irst Part In	spection	Record			
		1 Maintenance			Date Part Submitted	Time Of Day	Approved	Mtrl	Rev	Inspector	Notes		
		<ul><li>2 Tooling</li><li>3 Setup</li></ul>			Submitted	1.	Yes / No	Check	Letter	×	30 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
		4 FAIR											
		<ul><li>5 Training</li><li>6 Meeting</li></ul>											
CECOND A DV DDODUCTIO						DACE 1					Take Da	10/15/15	