Part No. Order No. Order Qty		FS1	35-10	Cor	Component		A02002-0022			ol.
		397455 \$80 600 P		Heat Lot #		A02002-0022			CD contradevice	es' rrc
								PS no	w 4min505	ee)
	HARMATA			OPERATIO		Note to the second			THRU-PUT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes	Scrap	Scrap Code
HARDING	2-8-16	20				3	3	Setup 1sto	P	
COBRA	2.8.16	BA	3.0	25	25			å		
Setup Hrs.	2/9/16	Bo	8	53	78					
3,0	2-9-16	50	5,0	32	116			×		
Cycle Time		BA	6.5	35	202					
gmi noid	2110100	197	8.0	17	010					
400 5000	2.10.16	BA	1.5	85	534					
Pcs/Hr	2/11/16	BJ.	7.5	61	395					
Old Janu	2111.16	BALID	80	87	442					
5/11	2/12/16	BT	6.5	52	534			All		
ROUTING:						READ ROLLE	R			
of the second	A back the back the			OPERATIO		Down	Down time		THRU-PUT/8HRS	Scrap
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	time	code	Notes	Scrap	Code
				28	562					*
	2.12.16	BA	,5	8	570					
Setup Hrs.	2/13/16	130	6	51	621					
	2-13-16	20	,5	8	629					
	10								Λ	
Cycle Time								16.	1	
				-				1		
Pcs/Hr			-)				125		
гсз/пі								+5		
			-						- 10	
ROUTING:										
		LA VALORIA		OPERATIO	N 3				THRU-PUT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes	Scrap	Scrap Code
Colorg					7.5					
andop										
Setup Hrs.										
Cycle Time						iii.				
Pcs/Hr								¥.		
										
ROUTING:										
Notes / Instructions		Down Time Codes		N N				pection Record		
1		1 Maintenance2 Tooling		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev Letter Inspector	Notes	
		3 Setup		2-8-16	5:25	V NO	CHECK	A J.C		
		4 FAIR 5 Training					1	/		
		6 Meeting								
ECONDARY	PRODUCTIO	N RECORD			PAGE :	l,			Test Form :	10/15/15