Part No. Order No. Order Qty		399351 12	a	control devices, LLC	s, LLC		Component(s)	<u>(s</u>	<u> </u>	No(s) 399351	Heat Lot/Traceability No(s) 399351
	Disting	Distinguishing Traceablity Numbers	ity Numbers					C-RING	C-RING		
Flare Nuts	Six digit n	Six digit no. located on the box label under box quantity.	box label unc	der box quantit	y.		1 1				
<b>Brazing Rings</b>	Located o	Located on the box label, directly above the word "heat."	irectly above	the word "heat	t."						
Copper Tubing	Located o	Located on the spool label, starting with the letter "M."	starting with	the letter "M."							
Span Bings	Cac their	Ose their work order harmond by "Lot Nimbos"	d by "I at Nine	מור מוכי שטא ומטכו							
Snap Rings	Located o	Located on the bag followed by "Lot Number."	d by "Lot Nur	nber."			T				
Caps/Plugs	Do not red	Do not require traceability.					Г				
Mach. No.	0.		Setup Hrs.	Cycle Time			Pcs.	Pcs./Hr		Pcs./Hr Thru- put/8hrs	
Date Emp. Name	ne Prod Hrs.	Total Pcs.	Cum. Total	l Down Time	Down Time Code				Notes	Notes	Notes
9/4 SB		Ja.									
									7	209	
									3		
ROUTING:											7
Special Notes / Instructions	structions	Down Time C	Codes				First	First Part Inspection	First Part Inspection Record	First Part Inspection Record	First Part Inspection Record
		<ol> <li>Maintenance</li> <li>Tooling</li> <li>Setur</li> </ol>	Date Subn	Date Part Submitted Time Of Day	Approved Yes / No	Mtrl Check	Rev L	Rev Letter Inspe	Rev Letter Inspector	Inspector	Rev Letter Inspector Notes
BRAZING PRODUCTION RECORD	DECOBO				-						