| Part No. | 1102-1 | 1102-10-5/16-R | | J | ontrol | | | 2 | nonon+(c) | Heat Lot/Traceability | bility | |
|------------------------------|----------------------|--|---------------|--------------------------|---------------|-------------------|-------|---------------|---|-----------------------|--------|-------------------|
| Order No. | 40 | 400188 | | 4 | devices, LLC | LLC | | C | component(s) | No(s) | 1 | |
| Order Qty | | 10 | | | | | | 110 | 1102-10-5/16 | 60000h | | |
| | Distingu | Distinguishing Traceablity Numbers | ity Numb | ers | | | | 2 | C-RING | | | |
| Flare Nuts | Six digit no. | Six digit no. located on the box label under box quantity. | box label | under bo | ox quantity. | | | | | | | |
| Brazing Rings | Located on | Located on the box label, directly above the word "heat." | lirectly ab | ove the v | vord "heat." | | | | | | | |
| Copper Tubing | Located on | Located on the spool label, starting with the letter "M." | starting v | with the l | etter "M." | | | | | | | |
| Flare Tubes | Use their w | Use their work order number and date on the box label. | er and da | ate on the | box label. | | | | | | | |
| Snap Rings | Located on | Located on the bag followed by "Lot Number." | ed by "Lot | Number. | ~ <u>#</u> | | | | | | | |
| Caps/Plugs | Do not requ | Do not require traceability. | 120 | | | | 9.10 | | | | | |
| | A THE REAL PROPERTY. | Name and Address of the Owner, where | | management of the second | | 医有牙疮点 | | | · 有一种,一种,一种,一种,一种,一种,一种,一种,一种,一种,一种,一种,一种,一 | | | |
| Mach. No. | | | Setup Hrs. | | Cycle Time | | | Pcs./Hr | | Thru- put/8hrs | | |
| Date Emp. Name | Prod Hrs. | Total Pcs. | Cum. Total | Total | Down Time | Down Time Code | | | Notes | | Scrap | Scrap Code |
| 2-11-10 LW | 8 | 01 | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | 1 | - | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | 011. | | |
| | | | | | | | | | | 75.0 | | |
| | | | | | | | | | | • | | |
| | | | | | | | | | | | Q | |
| ROUTING: | | | | 1 | | | | | | | Ĉ | |
| Special Notes / Instructions | ictions | Down Time Codes | odes | 200 | | | | First Part In | t Inspection Record | | | |
| | | | | Date Part | | Approved | | | operation receive | | | |
| | | 2 Tooling | L | Submitted | Time Of Day | Yes / No | Check | Rev Letter | Inspector | Notes | is. | |
| | | | | | | | | 1 | | | | |
| | | 5 Training | | | | | | | | | | |
| | | | | | | | | | | | | |
| BRAZING PRODUCTION RECORD | ORD | | | | | | | | | | Test F | Test Form 11/4/15 |