Part No.	0.	2803	2803-11-1/4						,		Heat Lo	Heat Lot/Traceability		
Order No.	Vo.	39	396783		A	devices, LLC	ררכ		Con	Component(s)		No(s)		
Order Qty	lty		2						280	2803-11-1/4-0	396	396390	_L	
		Distingu	Distinguishing Traceablity Numbers	ity Numb	ers				DO	DCN516-HT	2	NA		
Flare Nuts	uts	Six digit no.	Six digit no. located on the box label under box quantity.	box labe	under bo	ox quantity.				A-KF003	Z	NA		
Brazing Rings	lings	Located on	Located on the box label, directly above the word "heat."	directly ak	ove the v	vord "heat."								
Copper Tubing	gnidu	Located on	Located on the spool label, starting with the letter "M."	, starting	with the l	etter "M."								
Flare Tubes	bes	Use their w	Use their work order number and date on the box label.	er and d	ate on the	box label.								
Snap Rings	ngs	Located on	Located on the bag followed by "Lot Number."	ed by "Lot	. Number.	=								
Caps/Plugs	SBn	Do not requ	Do not require traceability.	67.00										
~	Mach. No.			Setup		Cycle		Description of the least of the	Pcs /Hr		Thru-			21 ×
				TIS.		Time					put/8hrs			
Date E	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Total	Down Time	Down Time Code			Notes			Scrap	Scrap
1-13	98		دو											
						100-000 %								
													9	
												2/4		
												11/63		
												163		
													2	
ROUTING:														
Special No	Special Notes / Instructions	ctions	Down Time Codes	odes					irst Part Ir	First Part Inspection Record				
			1 Maintenance		Date Part	!	Approved	Mtrl						
					Submitted	Time Of Day	Yes / No	500	Rev Letter	Inspector		Notes		
			 Iraining Meeting 	—т			: •							
BRAZING PRODUCTION RECORD	CTION REC	ORD											Test For	Test Form 11/4/15