Part No. Order No.		E10 388361		Component		A02001-0032			1	ØN V	contr	ol \	
				He	at Lot #	NA			control devices, Lc				
Ord	er Qty	10	000	W/0 #	from Box		73.		1			1	
		wilder The		OPERATIO						THRU	PUT/8HRS		
Mach No.	Date	Emp. Name		Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code	
H2	10-28-15	BA	9	091	352							*	
Setup Hrs.	10-29 15	IfUD		314	666	1							
	10-30-15	BA		189	855				_				
	10-30-15	HVD	9	3/5	E/17 7 1	70					0.50		
Cycle Time	10-3015	BA	8	277	1447	, ,					- /		
/M31s	11-2-15	HUD	8	293 70	1740			1)6	BOU	7	16		
Pcs/Hr	11.2.3	1700		70	1010				- 0	10	5		
									1)	1	~		
31									1		10		
ROUTING:						DEBURR							
<b>美術學科學</b>			Supplement A	OPERATIO	N 2	Down Down tir					PUT/8HRS	STATE OF THE PARTY	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	time	Down time code		Notes		Scrap	Scrap Code	
Setup Hrs.						<u> </u>							
Cools Tissa													
Cycle Time													
Pcs/Hr			-										
ROUTING:													
		<b>第三届新的</b> 《新教》(第三		OPERATION 3					THRU-PUT/8HRS				
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes			Scrap	Scrap Code	
						time						couc	
Setup Hrs.			_	(I)									
ŀ		11111							90			r	
Cycle Time						0.	17.						
-joic rane													
ŀ								~					
Pcs/Hr			-1100 F3										
ROUTING:													
	structions	Down Ti	ime Codes			F	irst Part In	spection	Record				
		1 Maintenance		Date Part	Part Time Of Day Approved			Mtrl Rev Inspector			Notes		
		<ul><li>2 Tooling</li><li>3 Setup</li></ul>		Submitted	5 C. Duy	Yes / No	Check	Letter	Порессот		Hotes		
		4 FAIR											
		<ul><li>5 Training</li><li>6 Meeting</li></ul>		-							11-14-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		
		O WICCHING			1				1				