Orde Orde	er No.	391		Component		A02071-0040			1	D. H. etc.	dovice	36 116
Orde	r Oty	391390		Heat Lot # W/O # from Box OPERATION 1					CD control devices, L.C			
CHEROMORPH .	i Qty	10										
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down	Down time code		Notes	THRU-	Scrap	Scrap Code
H3	11-23-15	BA	6.5	416	585							
Setup Hrs.	11-21-12	pre r	-	101	5 0)					20		
ə -								V	1 0B06-) H	UD		
Cycle Time						1			12			
534								7 1		6		
Pcs/Hr									2 00	My.		
61									19-05	2	0	
ROUTING:								l				
3 5 7 1 5				OPERATIO	N 2					THRU-	PUT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
-												
Setup Hrs.								3:			2	
Cycle Time	10.00											
Pcs/Hr												
			_									
ROUTING:				ODEDATIO	N O							
ALEXE OF THE STATE OF					OPERATION 3		Down Down time				-PUT/8HRS Scrap	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	time	code	******	Notes	*	Scrap	Code
							1 12					
Setup Hrs.												-
									No.			
Cycle Time												_
Pcs/Hr												
L												
DOUTING				L								
Notes / In	structions	Down T	ime Codes			-	irst Part In	spection	Record			
Notes / III	Jer detions	1 Maintenand		Date Part	MAN, SERVICE	Approved	Mtrl	Rev			2007 0	
2		2 Tooling		Submitted	Time Of Day	Yes / No	Check	Letter	Inspector	CD	Notes	
		3 Setup 4 FAIR		11-2445	6:45	455	0	A	Dit	#09	ALV TEN	
		5 Training				,						
SECONDARY		6 Meeting			PAGE	MINING THE RESIDENCE OF THE PERSON OF THE PE					Test Form	