Control Devices LLC
Work Order Production Record

Part No.	P5075001-02
Order No.	324813
Order Qty	

Machine No.	1
Rev Letter	F
Planned Pcs/Hr	10
Remaining Loads	#DIV/0!

Wgt/Bar		Total Bars	#DIV/0!
Bars/Load		Total Loads	#DIV/0!
Wgt/Pc		Pcs/Bar	#DIV/0!
Component	P5075001-		

Setup Allowed Hrs.	
Setup Actual Hrs.	0
Setup %	######

Date	Emp. Name	Clock #	Prod. Hours	Setup Hours	Total Pcs	Pieces Today (bars)	Planned Hours	Cum. Total	Balance Due Pcs	Plan Pcs/Day	Actual Pcs/Day	% Mach. Efficiency	Material Heat Lot No.	Mach Down Time	CODE	Scrap Pcs.	Notes
		beginning balance						0	0								
2/28	Sm	1130	.5		1/2	0	0	0	0	0	0	#DIV/0!			0		1/8 27 D/TAP 2 places
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
			0	0	0	0								0		0	Page 1

Barstock Efficiency		Actual Efficiency		Down Time Codes		Total Hours
Total Planned Pcs	0	Total Counted Pcs		1	Maintenance	0
				2	Tooling	0
BarStock Efficiency	#DIV/0!	Actual Efficiency	#DIV/0!	3	Setup Idle	0
				4	Other	0
Total Barstock Pcs	0			5	??????	0

First Part Inspection Record

Date Part Submitted	Time Of Day	Approved Yes / No	Material Check	Inspector	Notes
2/26/14	6:30	YES	✓	DH	QA INSP #09