70		11-1	******				-			- U>>+ I>+/T		
Order No.	ó.	392	392769	O	devices, LLC	LLC		Com	Component(s)	No(s)	(s)	
Order Qty	ltγ	1	14					SF	SF7-2.5-22	393769	0	
		Distingui	Distinguishing Traceablity Numbers	ity Numbers				S	CSW-3-7/8	L		
Flare Nuts		ix digit no. I	ocated on the	box label unde	Six digit no. located on the box label under box quantity.			CUTU	CUTU-36-5/32-B			
Brazing Rings		ocated on t	he box label, d	irectly above t	Located on the box label, directly above the word "heat."				BRZ22			
Copper Tubing		ocated on t	he spool label,	Located on the spool label, starting with the letter "M."	he letter "M."			nee:	BRZ00			
Flare Tubes		Jse their wo	rk order numb	Use their work order number and date on the box label.	the box label.				CP15			
Snap Rings		ocated on t	he bag followe	Located on the bag followed by "Lot Number."	ber."							
Caps/Plugs	А	o not requi	Do not require traceability.									
	nach No		AT A COLUMN TO SERVICE	Setup	Cycle) III.		Thru-		
	a de la constante de la consta			Hrs.	Time			FG:/111		put/8hrs		
Date Er	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down Time	Down Time			Notes		Scrap	
						Code						Code
dife	A	040	14	14							8	
,				-							0	
												+
					<u></u>						5	
>										2		
										12/10	Ş	
										70	2	
POLITING:												-
Special No	Special Notes / Instructions	tions	Down Time Codes	odes			Fi	First Part In	Part Inspection Record		8.	
		1	Maintenance	Date Part	_	Approved	Mtrl	ev letter	nenector)	Notes	
		2	Tooling	Submitted	ted Time Of Day	Yes / No	50%	Kev Letter	Inspector	co	Notes	
		. ω	Setup	12:10-	x 20x	UKS	1	C	#	(60#)		1
		л 4	FAIR		0	1		Q	111			
		6 (Meeting					4				
BRAZING PRODUCTION RECORD	CTION RECO	כפ										