Part No. Order No.		G2A 400045		Component Heat Lot #		GA-BLNK			control devices, LLC			
PMARSA				OPERATIO			ZA PERMIN	100-60		THRU-	PUT/8HRS	216
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
BLUE LATHE	2-10-16	HVD	105	l	1	0	0	J	du T		0	0
Setup Hrs.									YVV			
5				,			_					
Cycle Time												
2 MIN									116	0		
Pcs/Hr								1	1			
27								P	55		A	
ROUTING:												
				OPERATIO	N 2	MANE PROMIS				THRU-PUT/8HRS		
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
Setup Hrs.			- 27									
							_					
Cycle Time												
- 1											7	
Pcs/Hr										-		
РС5/ПІ												
ŀ										\rightarrow		
ROUTING:												
Mark School	建筑市场			OPERATIO	N 3		y with u bit		XQ, HAX	THRU-P	UT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes			Scrap	Scrap Code
Setup Hrs.											***	
setup nrs.												
ŀ									1011			
Cycle Time)				
Pcs/Hr												
ROUTING:												
	structions	Down Ti	me Codes			-	irct Part Inc	nostion P	ocord			
, 11		1 Maintenance	THE RESERVE TO SERVE THE PARTY OF THE PARTY	Date Part		Approved	irst Part Ins Mtrl	Rev				1000
		2 Tooling		Submitted	Time Of Day	Yes / No	Check	Letter	Letter Inspector		Notes	
		3 Setup 4 FAIR		2-10.16	9:45	(125		A	pt of	C. C. C.	3	
		5 Training				1/5			9	**0		
ECONDARY	PRODUCTIO	6 Meeting N RECORD			PAGE 1						Tast Form 1	0/45/45