PRIMARY PRODUCTION RECORD Order No. control devices. Order Qty Part No. Date Emp. Name , LEC 3,000 X \Box FOR DAVENPORTS & BROWN & SHARPES ONLY: To Figure Pieces From Loads = Pcs/Bar x Total loads ran during shift x Bars per load Prod. Hours TOTAL PCS. PRODUCED 0 12 W Total Pcs Special Notes / Instructions Standard Actual 3020 Cum. Total Planned Pcs/Hr 9/952 Material Heat Lot No. Actual Pcs/Hr Thru-Put/8Hrs First Part Inspection 623 Record Date Part Submitted Down Component Wgt/Bar Wgt/Pc. Down Time Code W Time of Day 0.013 5.73 A02001-0013 Approved Mtrl Rev Yes/No Check Letter Notes - Maintenance
- Tooling
- Setup
- FAIR
- Training
- Meeting Inspector TOTAL SCRAP PCS. Setup Allowed Hrs. Pcs./Bar Notes Mach No. Scrap Pcs. Scrap Code 441 7