				The second second second		W of the second		1/				
Part No.		AR15		Component Heat Lot #		AR-BLNK				CD con	trol	
Order No.		397478								devi	ces, LLC	
Ord	ler Qty		3		from Box							
Mach No.	Date	Emp. Name	Prod Hrs.	OPERATION Total Pcs.	ON 1 Cum. Total	Down	Down time		Notes	THRU-PUT/8H Scrap	Scrap	
Bluc	1-19-16	HUN	.5	3		time			¥		Code	
Setup Hrs.							1				_	
5 MIN					_							
Cycle Time							1					
2 MIN								,	1	10		
Pcs/Hr									VP	6.5	1	
27										P		
ROUTING:							1	-				
	(1)			OPERATIO	N 2		ST. Walls	25 miles		THRU-PUT/8H		
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes	Scrap	Scrap Code	
						1						
etup Hrs.									, w			
ycle Time												
5 (11												
Pcs/Hr												
OUTING:												
e inte				OPERATIO	N 3	5/90 (19)			47 - 47	THRU-PUT/8HF	RSI	
/lach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes	Scrap	Scrap Code	
etup Hrs.											ı	
cle Time												
cie Tillie									-19-2			
- 1												
Pcs/Hr								٠				
					_				130			
OUTING:												
Notes / Ir	nstructions	_	me Codes				irst Part In		n Record			
		1 Maintenance2 Tooling		Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev Letter	Inspector	Notes		
		3 Setup		1-20-10	PAL PAL	425	CHECK	A	At 6.9			
		4 FAIR 5 Training				(11	#0			
CONDARY	PRODUCTIO	6 Meeting	10 To		DACE			9				
CUNDARY	PRIMITE HILL	NECORD			DACE	1				and the second s	COLUMN TO A COLUMN	