| Part No. | 705-2 | 705-12-1/4-R | | | , and a | | |) | | Heat Lot/ | Heat Lot/Traceability | | |
|---|---------------|--|---------------|------------|---------------|-------------------|------|---------------|-------------------|-------------------|-----------------------|----------|-------------------|
| Order No. | 39 | 394466 | | H | devices, LLC | LLC | | Con | Component(s) | Z | No(s) | | |
| Order Qty | | 3 | | | | | lir. | 70 | 705-12-1/4 | N/A | <i>7</i> 5 | ! | |
| | Distingu | Distinguishing Traceablity Numbers | lity Numb | ers | | | | , | G-RING | 4081S10E | F08 | | |
| Flare Nuts | Six digit no. | Six digit no. located on the box label under box quantity. | box label | under bo | x quantity. | | | | | | • | | |
| Brazing Rings | Located on | Located on the box label, directly above the word "heat." | directly ab | ove the v | vord "heat." | | | | | | | 1 | |
| Copper Tubing | Located on | Located on the spool label, starting with the letter "M." | , starting v | with the l | etter "M." | | | | | | | | |
| Flare Tubes | Use their w | Use their work order number and date on the box label. | er and da | ate on the | box label. | | | | | | | | |
| Snap Rings | Located on | Located on the bag followed by "Lot Number." | ed by "Lot | Number. | iii | | | | | | | | |
| Caps/Plugs | Do not requ | Do not require traceability. | • | | | | | | | | | | |
| ALL II TO A STATE OF THE STATE | | | | | | | | | | | | | |
| Mach. No. | | | Setup Hrs. | | Cycle Time | | | Pcs./Hr | | Thru- put/8hrs | | | |
| Date Emp. Name | Prod Hrs. | Total Pcs. | Cum. Total | Total | Down Time | Down Time Code | | | Notes | | S | Scrap | Scrap Code |
| 98 11/21 | | ເນ | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | c . | | |
| | | | | | | | | | | | 5 | | |
| | | | | | | | | | | | 1 | | |
| | | | | | | | | | | 1 | | | |
| | | | | | | | | | | 1000 | • | | |
| | | | | | | | | | | | | ? | |
| | | | | | | | | | | | | Z | |
| ROUTING: | | | | | | | | | | | | (| |
| Special Notes / Instructions | ictions | Down Time C | Codes | | | 24 Man | | First Part In | Inspection Record | | | | |
| | | 1 Maintenance | | Date Part | Time Of Day | Approved | Mtrl | | Inspector | | Notes | | |
| | | | | Submitted | Tillie OI Day | Yes / No | | ven rettel | IIIspector | | Notes | | |
| | | | _ | | | | | | | | | | |
| | | 6 Meeting | | | | | | | 100 | | | | |
| BRAZING PRODUCTION RECORD | ORD | | | | | | | | | | | Test For | Test Form 11/4/15 |