Part No.	No.	F401-3	F401-3-3/16-3/4			7)		Heat L	Heat Lot/Traceability		
Order No.	r No.	39	392765		A A	devices, LLC	LLC		Com	Component(s)		No(s)		
Order Qty	Qty		1						SF4	SF401-3-3/16		AMA		
		Distingu	Distinguishing Traceablity Numbers	lity Numb	pers				_	BRZ03		0/10		
Flare Nuts		Six digit no.	Six digit no. located on the box label under box quantity.	box labe	l under bo	x quantity.			0	CFT-1/2		10/10		
Brazing Rings		Located on	Located on the box label, directly above the word "heat."	directly al	bove the w	ord "heat."	•		_	FLR-1/2		NB		
Copper Tubing	Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting	with the k	etter "M."				L3/4		NA	•	
Flare Tubes	Tubes	Use their w	Use their work order number and date on the box label.	er and d	ate on the	box label.				L-RING				
Snap Rings	Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lo	t Number.			T						
Caps/Plugs	Plugs	Do not requ	Do not require traceability.	135									•	
	School separate particular	Andrew Spirit Street	Principle of the California			THE PART OF STREET					The second second second		San September 1	
	Mach. No.	V		Setup Hrs.	@ Im	Cycle Time	3		Pcs./Hr		Thru- put/8hrs			
Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum.	Cum. Total	Down Time	Down Time Code			Notes		Scr	Scrap	Scrap
12-4-K	HUH	0)										J	
		(8)								10000)		ı		
									9	L				
											1	,		
		91									7			
											-			
										-	5	Α.		
											4			
												7	7	
ROUTING:														
Special	Special Notes / Instructions	tions	Down Time Codes	odes				TI	First Part Ins	rt Inspection Record				
		1 2	Maintenance Tooling		Date Part Submitted	Time Of Day	Approved	Mtrl P	Rev Letter	Inspector)	Notes	¥	_
		3			アナイ	1122	150	1		74	(a) (b)			
		4.					4		()		4			
		6 U	Meeting					0	1					
BRAZING PRODUCTION RECORD	OUCTION RECO	ORD											Test Form 11/4/15	11/4/15
													100110111	