Part No.	AS	ASC-11-7		control		Com	Component(s)	Heat Lot/Traceability	aceability	
Order No.	39	392590	î	devices, LLC	C	Coll	ponent(s)	No(s)	s)	
Order Qty		25				1	ASC-11	1/1	7"	
	Disting	Distinguishing Traceablity Numbers	lity Numbers			0	CASC-11	NA		
Flare Nuts	Six digit no	located on the	Six digit no. located on the box label under box quantity.	ox quantity.			BRZ00	1/8		
Brazing Rings	Located on	the box label, o	Located on the box label, directly above the word "heat."	word "heat."						
Copper Tubing	Located on	the spool label	Located on the spool label, starting with the letter "M."	letter "M."						
Flare Tubes	Use their w	ork order numl	Use their work order number and date on the box label.	ne box label.						
Snap Rings	Located on	the bag follow	Located on the bag followed by "Lot Number."	7.		ž/i				
Caps/Plugs	Do not requ	Do not require traceability.								
										J
Mach. No.	BH		Setup Hrs. 30M	Cycle Time	3	Pcs./Hr		Thru- put/8hrs		
	Mar Differ or William			(Application)	Timo					
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down Time	Down Time Code		Notes		Scrap	
July 15-12-61		38								_
							10000			$\dashv$
						(	10000			-
										Н
										+
					+			5		_
								かけ、かな		H
								+ 17 7	J	+
								1		-
										-
									)	
BOITING:					-					-
Special Notes / Instru	ctions	Down Time (	Codes			First Post	in Provide			П
Special Motes / Histi detroits	CLIOITS	DOWN TIME	-		1		First Part Inspection Record			
		<ol> <li>Maintenance</li> <li>Tooling</li> </ol>	Date Part Submitted	Time Of Day	Approved Mtrl Yes / No Check	<b>\</b>	Inspector		Notes	
		3 Setup 4 FAIR	12-4-15	Ilma	- 1		Y SO			
						Z				