## **ACTION ALERT**

PART #_ CT_50 [ ]
CONCERN NO CHAMFER ON LEAD THREAD
VERIFY CHAMFER PRESENT ON LEAD OF
THECAN
Name: 1. / 10km Date: 3/24/10
CONTROLLED CDF011