	CO. ST. ST. ST. ST. ST. ST. ST. ST. ST. ST								meat Lot/ iraceability	CEADIIILY	
Order No.	40	400903	<b>‡</b>	devices, LLC	LLC		Comp	Component(s)	No(s)	<u>ت</u>	
Order Qty		2				<b>—</b> 1	2203,	2203A-3-1/4-0	39984	86	
	Disting	Distinguishing Traceablity Numbers	lity Numbers				DCN	DCN316-HT	( )		
Flare Nuts	Six digit no	Six digit no. located on the box label under box quantity.	box label unde	er box quantity.			Α-	A-KF004	7		
Brazing Rings	Located on	the box label, o	directly above t	Located on the box label, directly above the word "heat."	17/24						
Copper Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting with t	he letter "M."							
Flare Tubes	Use their w	Use their work order number and date on the box label	per and date on	the box label.							1
Snap Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lot Num	ber."							
Caps/Plugs	Do not requ	Do not require traceability.	• 22								
Mach. No.			Setup Hrs.	Cycle Time			Pcs./Hr		Thru- put/8hrs		
Date Emp. Name	e Prod Hrs.	Total Pcs.	Cum. Total	Down Time	Down Time Code			Notes		Scrap	Scrap Code
2117		با									
8											
•						e.T					
										0	
									, (		
									CUL		
									3		
								n		2	
ROUTING:										(	-
Special Notes / Inst	/ Instructions	Down Time (	Codes			n	est Part Inc	pection Record			
openior money mo	er occiono	Cowin mine	-			4	St Part IIIS	riist Part irispection Record			
		<ol> <li>Maintenance</li> <li>Tooling</li> </ol>	Date Part Submitted	art Time Of Day	Approved Yes / No	Mtrl R	Rev Letter	Inspector		Notes	
		5 Training					T -				