Control Devices LLC
Work Order Production Record

Machine No.	CNC
Rev Letter	A
Planned Pcs/Hr	

Wgt/Bar			
Bars/Load		Total Bars	#DIV/0!
Wgt/Pc		Pcs/Bar	#DIV/0!
Component	1/2 Brass		

Setup Allowed Hrs.	
Setup Actual Hrs.	0
Setup %	#####

Part No.	BOV 20014
Order No.	319008
Order Qty	50

Date	Emp. Name	Clock #	Prod. Hours	Setup Hours	Total Pcs	Pieces Today (bars)	Planned Hours	Cum. Total	Balance Due Pcs	Plan Pcs/Day	Actual Pcs/Day	% Mach. Efficiency	Material Heat Lot No.	Mach Down Time	CODE	Scrap Pcs.	Notes
		beginning balance						0	0								
1-3-14	DPM	27701	2.0	6.0	22	0	0	0	0	0	0	#DIV/0!					PROGRAMMED & SETUP
1-7-14	DPM	27701	3.3		38	0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
						0	0	0	0	0	0	#DIV/0!					
			0	0	0	0	0							0		0	Page 1

Efficiency	
Total Planned Pcs	0
fficiency	#DIV/0!
Total Piece Count	0

Total Counted Pcs

Down Time Codes		Total Hours
1	Maintenance	0
2	Tooling	0
3	Setup Idle	0
4	Other	0
5	Alternate - Tooling/ Units/ S/U	0

First Part Inspection Record

Date Part Submitted	Time Of Day	Approved Yes / No	Material Check	Inspector	Notes