

6. MATERIAL TO BE STRESS RELIEVED (550°F FOR 1

7. INSIDE CAVITY OF DISTRIBUTOR TO BE BEAD

BLASTED TO REMOVE ALL BURRS AND

HOUR MIN)

SHARP EDGES

.187

.236

.291

.240

.250

.312

1301-#-1/4

1301-#-5/16

1301-#-3/8

19 TO 24

16 TO 20

13 TO 16

.254

.317

.379

MATERIAL

SEE NOTE 6

UNS C36000 H02 BRASS

DO NOT SCALE DRAWING

2.285 LBS

SCALE 1:1

1301-A-BLNK

SHEET 1 OF 1