Part No. Order No. Order Qty		P1212001-10 391984		Component		A02002-0060		0	contr	ol	
				He	Heat Lot #			Cycle	Cycle dime is		
				W/O # from Box		+		now Zm	me is	. 10	
A Mile Tools				OPERATION	ON 1				U-PUT/8HRS		
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time	Notes	Scrap	Scrap Code	
OKUMA	2.5.16	BA		3	3	4.0	3		c io	Code	
	2-16	50	3.0	10	13	3,0		worked on sort ins too)	V		
Setup Hrs.	- 11 11	BA	6.0	30	43						
	2/8/16	185	8	38	81	1 ~					
Cycle Time	2.8.16	00	7.0	35	116	1,0		Shorten cycle time			
Omin	2/9/11	Off	0.0	33	192	-			_		
1 rsec	2-9-16	200	6.5	25	719	-			-		
Pcs/Hr	2.9.16	BA	80	48	267						
	2/10/16	80	6.0	35	302						
5	2-10-16	50	1.0	8	310				•		
ROUTING:											
Mach No.	Date	Emp. Name	Prod Hrs.	OPERATION Total Pcs.	Cum. Total	Down	Down time	Notes	U-PUT/8HRS Scrap	Scrap	
	0.10 1/-	Q VI	00	.39	2119	time	code	Notes	эсгар	Code	
HARDING COBRA	2/11/14	135	0.0	33	541						
Setup Hrs.	201110	70	6.5	15	382				+		
	2.11.16	RA	2,0	29	431						
	2/12/16	138	5	24	455			Λ			
Cycle Time	2-12-16	50	1.5	9	464			()()			
	2.				10/		70	007			
								*			
Pcs/Hr											
ROUTING:			W								
NOOTING.	6650 AND TO		Kirdki Kir	OPERATIO	N 3	MENSIST.	by Median	THR	U-PUT/8HRS	80	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code	Notes	Scrap	Scrap Code	
m 02	2/12/16	BT		11	1/	5	3	_		Couc	
lne 07	2.18.16	20	2.5	16	27		3		1100		
etup Hrs.	2-12-16	BA	1	4	36	.5	3		10		
	2-13-16	BJ	6	51	82			2 7 0			
	2-13-16	70	9,0	36	118			1-10	,		
ycle Time	2.10.16	RH	le	38	156			5			
min	2/15/16	BT	8	7/	227		- 8				
Pcs/Hr	2-15-16	5 M	5	45	273		1	4			
1 ()	0-15-16	7200	80	15	345						
11-1	2/10/4	50	55	24	408				O		
ROUTING:	A IP LY				100						
Notes / I	nstructions	Down Ti	me Codes			F	irst Part Ins	spection Record	THE STATE OF		
		1 Maintenance 2 Tooling		Date Part Submitted	I Time Of Day I		Inspector	Inspector Notes			
	Ψ'.	3 Setup		25 II	10:45	Yes / No	Check	Letter	2007.01 (18-57-58-52-5)		
		FAIR Training		2-12-16	S TO AM	Sp.	1		DOP		
				mis.		0 -		7			
	/ PRODUCTIO	6 Meeting		W.		1					