Part No.		100046-1 3		Component		100046-999				@ Some control			
Order No.		396279 40		Heat Lot #		-				Control devices, LLC			
Order Qty		13		W/O # from Box					TB	B NO 1		Parts	
100 PM		公司的 提出得1		OPERATIO	ON 4	THE R. P. LEWIS CO., LANSING, MICH.		禁制提前		THRU	-PUT/8HRS		
Mach No.		Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code	
32	3/9/16 3-9-16	20	2.0	10	16	14	3						
Setup Hrs.		0 0		7 0	10								
•		†						-		-			
								+					
Cycle Time							-						
						1							
								ŧ					
Pcs/Hr								1					
							-	-					
ROUTING:			L					J					
為為政治	STATE OF STATE	建设备 传染	647725	OPERATIO	N:5		海拉拉斯		es Lisario	THRU	-PUT/8HRS		
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code	
	3-9-16	30	4,0	13	13	1,6		246	op com	dete			
	3.9.16	BA	1.0	2	15.				7 7				
Setup Hrs.													
Cycle Time													
											_		
Pcs/Hr													
)												
		_											
ROUTING:	SEPERATE STATES	Mark State of State of	Buch Hall Line	left telephone to a	02/25/57/02/02/02/57	Shirt with	Andrew State	112 4191	HERSEL MARKET	SELL MENTS OF	a fala de variante	61 A	
Mach No.		Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down	Down time		Notes	A PARTY OF THE PAR		Scrap	
						time	code		The Color Breezeway	,	Scrap	Code	
	3.9.16	BA	4.5	14	14	2.0	3/2		poles	- 4	7 tixte	PE-	
·	3/10/16	BT	.5	1	15	2	31	made	Arborla	osp£			
Setup Hrs.													
									1	2			
Cycle Time										//			
ycie rime									JV	Λ.			
ŀ													
Pcs/Hr									()V				
FCS/FII									0	10	100		
ł		+							2	-	1		
ROUTING:									2.6	\supseteq			
Notes / Instructions Down Time Codes First Part Inspection Record											्रांट (आ क		
		1 Maintenance		Date Part	The 200	Approved	Mtrl	Rev				(4) 10-21	
		2 Tooling		Submitted	Time Of Day	Yes / No	Check	Letter	Inspector	r Notes			
		3 Setup 4 FAIR											
		5 Training											
		6 Meeting											