Part No.		7-3-18		Component		7-	3-E	-BIN	BNK		control devices, LLC	
Order No.		395362		Heat Lot #					_[6 2 6	a device	es, LLC
Ord	er Qty	5			from Box	386	461					
国际分别与国际	incarata de la companya de la compa	新国内的基本的企业		OPERATIO		Down	Down time		地主动和社会	THRU	-PUT/8HRS	Scrap
Mach No.	Date	Emp. Name		Total Pcs.	Cum. Total	time	code		Notes		Scrap	Code
1999	12/30/15	C5	1.5	47	3	60	3				/	//
Setup Hrs.	12.0							3				
6 m	1-4-16	es	5.5	33	78							
Cycle Time	1-6-16	PS	3.5	8	86							
13/2 min	1-6-16	56	8	35	121			Jo	13-0u	1		
Pcs/Hr				*			1	1	214)			
		_						(#	7	(1)		
									114	55		
ROUTING:												
A REAL PROPERTY.	北州市市 1947年		CASE AND DESCRIPTION OF THE PARTY NAMED IN COLUMN TWO IS NOT THE PARTY NAMED IN COLUM			Down	Down time		had which had the	THRU-	PUT/8HRS	Scrap
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	time	code		Notes		Scrap	Code
		21										
Setup Hrs.												
Setup IIIS.												
							i					
Cycle Time												
										_		
Pcs/Hr								8				-
						_						
	i i											
ROUTING:	projekte skiede folde strekt	at the less of the large	Dec Southern 1920s	ODEDATIO	NI 2 rest transless	en C. Frieder Strand	a Serve on the One	different project	and the second second second	TUDU	DUT/QUDE	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	N 3 Cum. Total	Down time	Down time code	Notes		THKU-	Scrap	Scrap Code
				ē.	***************************************				_3			
Setup Hrs.												
				_		The state of the s						
Cycle Time					1							
			_									
Pcs/Hr						×						
1 (3) [1]												
1												
ROUTING:												
Notes / Instructions Down Time Codes First Part Inspection Record												
		 Maintenanc Tooling 	e	Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev	Inspector		Notes	
		3 Setup		12-29-15	10pm	Yes / No	Check	Letter	Letter			
		4 FAIR 5 Training			1000	-		1	N. Control of the con		_	
		6 Meeting										
SECONDARY	PRODUCTION	NI DECORD			PAGE 1						Tost Form	Olerian