Part No. Order No.		CSW-	CSW-3-7/8		Component		Cl	TI	1-3-	7/00			
		3959910			He	at Lot#		CUTU-3-			- 1	GD control devices, LL	
Orde	er Qty	19			W/O	# from Box					7	manus dorne	700, 22,
					ATION 1		MA THE	E A	handah k		THRU	-PUT/8HRS	
MACH NO.	o Turret	Lathe	SETUP HRS	0		CYCLE TIME	0			PCS/HR	0		
Date	Emp. Name	Prod. Hrs	Total Pcs.	C	ium. Tota	l Down Time	Down T Code			Notes	5	Scrap	Scr
CUM. TOTAL FRO							S	SCRAP TOTAL		FROM PREV. PAGE			Cod
1-6-16	JB		92		92				Jok	005	t		
				_									
				-									
										,			
				-		- 2	-	-					
													_
						1	+						
							1						-
													+
													+
	_												1
							-	_					
						-		_					
								+				-	-
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					+					
								\dashv				•	
								7					
			_										
						_							
								_					
							1	4					
			Supplies -					+			11 0		
		11-						+			NU		
							<u> </u>	+		\	11.		
								\dagger		1	50		
								\dagger					
								1					
ROUTING:		Davis T		_									
Notes / Instructions 1		Down Time Codes Maintenance		Г	ate Part		mo Of Day Approve			ection Reco		-	
	2			St	ubmitted	Time Of Day	Yes / No		Atrl Check	Rev Letter	Inspector	Not	tes
3 4		Setup FAIR			6-16	an	150		1	M.	M	#509 B	
	5	Training Meeting		-				+	-	MA	. 1	•	
ONDARY PR	ODUCTION RI	ECORD				PAGE	2					Test Form	