Part No. Order No. Order Qty		1304-32-1/4 402562		Component Heat Lot #		1304-A-BLNK 388476				( <del>-</del> )1	contr	ol
									41			-
Ora	er Qty		16	OPERATIO	from Box	58	841	6	W	M THRU-I	PUT/8HRS	16
Mach No.	Date	Emp. Name		Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
8	3-1-16 3-7-16	DG DG	2	8	12							
Setup Hrs.	3-8-16	CS	4-5	7	19			2				
12 MIN					3		, _	1		1		
Cycle Time					h D	0	1					
32 MIN										1/1	P	
Pcs/Hr									201	16		
2								+	0	9	A	
ROUTING:	n nur ik											
				OPERATIO	N 2	Doug	BOUNDAMES -	terest of the	<b>建一次自由</b> 数	THRU-F	PUT/8HRS	C
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
									1			
Setup Hrs.	:							-			1	
Cycle Time												
- "												L.
Pcs/Hr												
ROUTING:												
NOOTING.	The state of	THE RESERVE		OPERATIO	N 3			and the	1 Table 1	THRU-P	UT/8HRS	
Mach No.	Date	Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Down time	Down time code		Notes		Scrap	Scrap Code
Setup Hrs.			ii e							-		
Cycle Time												
Pcs/Hr								1 9			= -1	
00117777												
Notes / Ir	nstructions	Down T	imo Codos				lest David		Dan I			
Notes / Instructions		Down Time Codes  1 Maintenance		Date Part	D. D. I. Americal I. M.			spection Rev	Record			
		2 Tooling	12	Submitted	I IIma (It I)av		Approved Mtrl Yes /-No Check		Letter Inspector		Notes	
				15	500	1						
		3 Setup 4 FAIR		3-1-16	20	Y		0	att			
		3 Setup 4 FAIR 5 Training		3-1-16	20	Y		C	att		llee.	