Part No. Order No. Order Qty		CY11101 385984 25339		Component Heat Lot # W/O # from Box		CY11101-10		(T)	contro		
						The state of the s			G2	ontro devices	S. LLC
						359981 1 3720		276			
			OP	PERATION 1	Levers				THRU-PI	JT/8HRS	
MACH NO.	DP 0460		SETUP HRS	0 111	CYCLE TIME	10 50	20.	PCS/HR	588	1	
Date	Emp. Name	Prod. Hrs	Total Pcs.	Cum. Total	Down Time	Down Time Code		Notes	7	Scrap	Scrap Code
Ballo	ance Fo	rual	01-	1546		Sevar	Bal.	Forwa	vd	8	
11-3-15		26	285	1831						7/	2.2
11-9-15	CS	2.5	343 -	2788						4	22
11 (315)	C 3	3.4	J / J -								
11-10-15	CS	3	630	3618	-			10-5			
11-12-15	5 M	6:5	1361	4379							
1/-13-15	1	3,5	580	41959							
11-16	E.B.	4	(400	5559				145			
11-16	E.B.	8	752 1275	7584				-			
11-18	E.B.	1.5	200	7786							
11-17	5 m	4	700	8486				Δ.		A	
11-18	5M	6.5	1665	10148				M		200	
11/20/15	MK		1400	11548		/	#	1.1	f and	8"	
11-23-15	SM	7	300	13558	+651 		1	- 10	1000		/
11-24	NB	3.5	574	14.434			V	2000	1115		
11-25	RK	6	823	15257				= May	12411		
1/25/19	TIW. NI	1.5	225	15482				2 10	V/n,		6
11-30	SM	7	1579	17061				-			
12-9	RK	6		17723							_
2-15	CR	_3	300	18023						1	2
0 10	2.0					· ·	v	-			
								2			
								N			
								(1)			
							17-3	gra			
			1.60. 10.00.				0	5	-	155	
								71.0			
ROUTING:											
Notes / Instructions Down Time Co. 1 Maintenance			Date Part	First Part Inspection Record				rd			
		2 Tooling	.cc:	Submitted	Time Of Day	Approved Yes / No	Mtrl Check	Rev Letter	Inspector	Not	tes
*, •		3 Setup 4 FAIR		11.915	Ea	4155	-	The state of the s	4	RESET	
		5 Training6 Meeting						Α			
ECONDARY P	RODUCTION F				PAGE	1		Color Service		Test Form	10/15/15