Part No.	2803	2803-12-3/16			1			,		Heat Lot	Heat Lot/Traceability		
Order No.	39	396919		A	devices, LLC	LLC		Com	Component(s)		No(s)		
Order Qty		2					,	2803	2803-12-3/16-0	39	395414		
	Disting	Distinguishing Traceablity Numbers	lity Numb	ers				DC	DCN516-HT	Z	ZA	1	
Flare Nuts	Six digit no	Six digit no. located on the box label under box quantity.	box label	under bo	x quantity.			4	A-KF003	Z	NA		
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	directly ab	ove the v	ord "heat."								
Copper Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting v	with the l	etter "M."								
Flare Tubes	Use their w	Use their work order number and date on the box label	ber and da	ate on the	box label.								
Snap Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lot	Number.	=								
Caps/Plugs	Do not requ	Do not require traceability.										Ш	
	Control of the Special		Cotum	OCCUPATION OF THE PERSON	2				TO THE PERSON OF	+			
Mach. No.			Setup Hrs.		Cycle Time			Pcs./Hr		Thru- put/8hrs			
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Total	Down Time	Down Time Code			Notes			Scrap	Scrap Code
95 H-1		L.											
											>		
											Ç		
										1717	S		
ROUTING:											×	0	
Special Notes / Instructions	uctions	Down Time Codes	odes			1		First Part In	Inspection Record				
				Data Part		Approved	Ш		operation necessary				
				Date Part Submitted	Time Of Day	Approved Yes / No	Check	Rev Letter	Inspector	•	Notes		
		3 Setup											
								0					
		6 Meeting											
BRAZING PRODUCTION RECORD	CORD											Test Fo	Test Form 11/4/15