>> P1_3

coefficients =

6×2 table

n	а
0	12
2	-9600
4	1.28e+06
6	-6.8267e+07
8	1.9505e+09
10	-3.4675e+10

>>