```
% constants for HW5
clear all
close all
clc
syms y z
E1 = 30e6;
E2 = 10e6;
a1 = 6.5e-6;
a2 = 13e-6;
DT = 10*y^2+y^3;
PT =
 int(int(E1*a1*DT,y,-1.1,-.1),z,-.75,.75)+int(int(E2*a2*DT,y,-.1,1.9),z,-.75,.75);
MyT =
 int(int(E1*a1*DT*z,y,-1.1,-.1),z,-.75,.75)+int(int(E2*a2*DT*z,y,-.1,1.9),z,-.75,.75);
MzT =
 int(int(E1*a1*DT*y,y,-1.1,-.1),z,-.75,.75)+int(int(E2*a2*DT*y,y,-.1,1.9),z,-.75,.75);
PT = double(vpa(PT));
MyT = double(vpa(MyT));
MzT = double(vpa(MzT));
disp("If the temperature is applied then: ")
disp("PT = "+string(PT)+" lbs")
disp("MyT = "+string(MyT)+" lbs-in")
disp("MzT = "+string(MzT)+" lbs-in")
If the temperature is applied then:
PT = 6284.005 lbs
MyT = 0 lbs-in
MzT = 6342.4433 lbs-in
```

Published with MATLAB® R2022a