KrishanS Issued At: 23/03/2016 11:09 a.m. Requested By:

Reprint

Ship



Datacom Engineering Ltd

SH1603230035 To Warehouse: Jarred Green, Hamilton Ship List No.: **HNJG** From Warehouse: KrishanS Hamilton Central Store Shipped By: Orig. Doc.: SV1603220044@@1-1 Carrier: Document Type: Internal Order Carrier Ref. No.: Contact Person: Status: Ship list Open Contact Phone: Ν Currency: 115 Rostrevor Street Bill To:

Ship To:

Hamilton New Zealand

| Product | | Description | Qty | Serial No. | Bin/Area | Orig. Doc | Package |
|---|---|--------------------------------|-----|------------|----------|---------------|---------|
| 7MF22020404E00C(FS) | | Fujitsu 7000F TP7KF2 Base Unit | 1 | 46133 | FOODSTUF | SV1603220044@ | |
| | ' | | | | | | |
| Received By: <u>Jarred Green</u> Signature: | | Date: | | 23 / 3 | / 2016 | | |
| | | <u> </u> | | | | <u> </u> | |
| No. of Packages: | | | | | | | |

Out: 046025

0

Total Weight:

Fault: Base unit was running slowly. Rebuilt and tested. Lane has some weird config, uses id of lane 18 instead of 17 and hand scanner. Tested eftpos, printer, scanner and cashdrawer. All working. Nick from foodstuffs sys admin had to do some updates.