## MDX-650A/650 Unpacking and Repacking

**ACAUTION** 

Unpacking, installation, and moving must be carried out by five or more persons.


Failure to do so may result in falling of the unit, leading to injury. (The MDX-650A/650 weighs 120 kg (264.5 lb.).)

When moving, grasp the aluminum base portion at the bottom portion of the unit, and carry out the operation with five or more persons.


Failure to do so may result in falling of the unit, leading to injury.

## **How to Unpack**

The packings will be needed if you must repackage the product. Please do not throw them away.



Detach the retainers.



## **How to Repack**

- 1) Lower the spindle head all the way, then move to the center along the X axis.
- 2) Move the T-slot table all the way toward the front of the unit.
- 3) Repack by following the steps for "How to Unpack" in reverse.

