

Windows 8 Support Information

August 1, 2013

WINDOWS 8 SUPPORT INFORMATION

Color Software

Please refer to the chart below for Windows 8 compatibility and support information for color printing software. Software that is not listed in this document has not been tested and will not be supported on this new operating system.

Microsoft® Windows® 8 RT will not be supported.

	Microsoft® Windows® 8/Pro Edition		Full Windows 8 support
	32-bit (x86)	64-bit (x64)	planned?
Roland VersaWorks	Yes (Ver. 4.91)		
Roland OnSupport	Yes (Ver.1.61)		
Roland COLORIP	Not supported		No
Roland R-Works	Yes (Ver. 1.01)		
Roland BN Utility for Windows	Yes (Ver.1.20)		
Roland ColorChoice	Not s	supported	No

Printer Drivers

Microsoft® Windows® 8/Pro Edition		Full Windows 8 support
32-bit (x86)	64-bit (x64)	planned?
Yes (Ver. 1.20)		
Not supported		No
	32-bit (x86) Yes (32-bit (x86) 64-bit (x64) Yes (Ver. 1.20)

Note that VersaCAMM driver is not required if you are using Roland VersaWorks.

Cutting Software

Please refer to the chart below for Windows 8 compatibility and support information for 3D and Engraving software. Software that is not listed in this document has not been tested and will not be supported on this new operating system.

Microsoft® Windows® 8 RT will not be supported.

	Microsoft® Wind	Microsoft® Windows® 8/Pro Edition	
	32-bit (x86) 64-bit (x64)		planned?
Roland CutStudio	Yes		
Dr. Stika Plus	Yes		
Roland CutChoice	Not so	upported	No



Cutting Plug-ins

	Microsoft® Windows® 8/Pro Edition		Full Windows 8 support
	32-bit (x86)	64-bit (x64)	planned?
CutStudio Plugin for Adobe Illustrator	Yes		
CutStudio Plugin for CorelDRAW	Yes		

Cutting Drivers

	Microsoft® Windows® 8/Pro Edition		Full Windows 8 support
	32-bit (x86)	64-bit (x64)	planned?
GX-300/400/500/640	,	Yes	
GX-24	Yes		
CX-300/400/500	Not supported		No
CX-12/24	Not supported		No
SV-8/12/15	Yes		
SX-8/12/15	Not supported		No
STX-7/8	Not s	upported	No

3D and Engraving Software

Please refer to the chart below for Windows 8 compatibility and support information for 3D and Engraving software. Software that is not listed in this document has not been tested and will not be supported on this new operating system.

Microsoft® Windows® 8 RT will not be supported.

	Microsoft® Windows® 8/Pro Edition		Full Windows 9 support planned?
	32-bit (x86)	64-bit (x64)	Full Windows 8 support planned?
Roland iModela Controller	Yes (Ve	r.1.03)	
Roland iModela Creator	Yes (Ve	r.1.10)	
SRP Player	Yes (Ver	·. 1.22)	
MODELA Player 4	Yes (Ve	r.2.03)	
MODELA Player	Yes (Ve	r.4.05)	
MODELA 3D Design	Yes (Ver.1.42)		
MODELA 3D Text	Yes (Ver.1.22)		
Virtual MODELA	Yes (Ver.1.71)		
3D Engrave	Yes (Ver. 2.70)		
Dr.Engrave	Yes (Ver.2.72)		
R-WearStudio	Yes (Ver.1.20)		
ClickMILL	Yes (Ve	r.1.20)	



Roland EngraveStudio	Yes (Ver. 2.15)	
Roland JewelStudio	Yes (Ver.3.0SR2)	
VPanel for MDX PRO II	Yes (Ver.1.20)	
VPanel for MDX-40A	Yes (Ver.1.10)	Requires firmware ver.1.10 or later
VPanel for JWX-10	Not supported	No
VPanel for JWX-30	Yes (Ver. 1.10)	Requires firmware ver.1.40 or later
VPanel for DWX-50	Yes (Ver. 2.00)	Requires firmware ver. 2.00 or later
VPanel for DWX-30	Yes (Ver. 1.30)	

3D and Engraving Drivers

	Microsoft® Windo	ws® 8/Pro Edition	Full Windows 8 support planned?
	32-bit (x86)	64-bit (x64)	Full Williaows o support planned?
iM-01	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
EGX-20	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
EGX-30	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
EGX-30A	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
EGX-300	Not supported	Not supported	No
EGX-360	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
EGX-400/600	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
MDX-15/20	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
MDX-40	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	*Vpanel does not support Windows 8. Please upgrade to 40A.
MDX-40A	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
MDX-540/540A/540S/540SA	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
MDX-500/650	Not supported	Not supported	No
JWX-10	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
JWX-30	Yes (Ver.1.20.1)	Yes (Ver.1.03.1)	
RX-50	Not supported	Not supported	No
DWX-30	Yes (Ver.1.30)	Yes (Ver.1.10)	
DWX-50	Yes (Ver.1.30)	Yes (Ver.1.10)	

Impact Printing Software

Please refer to the chart below for Windows 8 compatibility and support information for Impact Printing software. Software that is not listed in this document has not been tested and will not be supported on this new operating system.

Microsoft® Windows® 8 RT will not be supported.



	Microsoft® Windows® 8/Pro Edition		Full Windows 8 support
	32-bit (x86)	64-bit (x64)	planned?
Roland METAZAStudio	Yes (V	er. 2.11)	
Roland SFEdit2	Yes (\	/er.1.02)	
Dr. METAZA	Not supported		No
Dr. METAZA 2	Not supported		No
MPX-90M Head Manager	Yes (Ver.1.10)		
MPX-90 Head Manager	Yes (Ver.1.10)		
MPX-80 Head Manager	Yes (Ver.1.10)		
MPX-70 Head Manager	Not su	ipported	No

Impact Printer Drivers

	Microsoft® Wind	Microsoft® Windows® 8/Pro Edition	
	32-bit (x86)	64-bit (x64)	planned?
MPX-90M	Yes (Ver.1.30)	Yes (Ver.1.20)	
MPX-90	Yes (Ver.1.30)	Yes (Ver.1.20)	
MPX-80	Yes (Ver.1.30)	Yes (Ver.1.20)	
MPX-70	Not su	upported	No

3D Scanning Software

Please refer to the chart below for Windows 8 compatibility and support information for 3D scanning software. Software that is not listed in this document has not been tested and will not be supported on this new operating system.

Microsoft® Windows® 8 RT is not supported.

	Microsoft® Windows® 8/Pro Edition		Full Windows 8 support
	32-bit (x86)	64-bit (x64)	planned?
Pixform Pro II	Yes (Ver.2.5.14.0)	Not supported	
Roland PixForm Pro	Not s	upported	No
Roland Pixform	Not s	Not supported	
Roland LPX EZ Studio	Yes (Ver.3.2)	Not supported	
Dr.PICZA3	Not supported		TBD
Dr.PICZA	Not supported		TBD
3D Editor	Yes (Ver.2.42)		
LPX Head Move	Yes (Ver.1.26)	Not supported	



3D Scanning Drivers

	Microsoft® Windows® 8/Pro Edition 32-bit (x86) 64-bit (x64)		Full Windows 8 support
			planned?
LPX-60	Not supported		TBD
LPX-600	Not supported		TBD
LPX-1200	Not sup	ported	TBD