

Distribution Integrity Management Program: 2026 Summary

Sedgewater Energy Holdings | Gas Engineering and Integrity | 2026-04-20

Annual summary of Sedgewater Gas Distribution's distribution integrity management program (DIMP) for 2026: system inventory, leak history, threat ranking and additional measures. Prepared by Gas Compliance with the Vice President, Gas Operations, April 20, 2026.

1. Program basis

A distribution integrity management plan must consider corrosion, natural forces, excavation damage, other outside force damage, material or weld failure, equipment failure, incorrect operations and other threats. This summary records how Sedgewater ranked those threats for 2026 and what it is doing about them.

2. System inventory at December 31, 2025

The system had 4,980 miles of main: 3,720 miles of polyethylene, 1,172 miles of coated and protected steel, 84 miles of unprotected steel and 4 miles of other, early-vintage plastic, with 251,000 services. 914 leaks on mains and services were repaired in 2025. The totals below are from the year-end inventory by district, material and installation decade.

Measure	main_miles
Unit	miles
Total	4980.0
Mean	41.5
Records	120
Period	2025-12-31 to 2025-12-31

Measure	services
Unit	services
Total	251000
Mean	2091.6667
Records	120
Period	2025-12-31 to 2025-12-31

Measure	leaks_repaired_2025
Unit	leaks
Total	914

Mean	7.6167
Records	120
Period	2025-12-31 to 2025-12-31

3. Leak history

In 2025 the company found 2,040 leaks: 164 grade 1, 551 grade 2 and 1,325 grade 3; 188 were caused by excavation damage. Non-excavation leaks by pipe material were 876 on protected steel, 761 on polyethylene, 204 on unprotected steel and 11 on other plastic.

Relative to main mileage, unprotected steel had about 243 non-excavation leaks per 100 miles of main, protected steel 75 and polyethylene 20. The rate uses all leaks on mains and services divided by main miles.

4. 2026 threat ranking

1. Excavation damage.
2. Corrosion on unprotected steel (roughly 85 miles of main).
3. Material, weld and joint failures in early plastics and older fittings.
4. Natural forces, mainly flooding and soil movement.
5. Equipment failure at regulators and meters.

5. Additional measures

Sedgewater is accelerating unprotected steel replacement, with the aim of removing it by the end of 2029; the 2026 target is 22 miles of main and 2,400 steel services. Remaining unprotected lines are surveyed every three years. Excavator outreach is concentrated in high-growth Crossroads areas, and crews inspect exposed facilities after major rain events.

The 4 miles of other plastic main have few leaks in absolute terms, but the sample is too small to compare leak rates reliably, so the ranking treats early plastics together with older fittings.

6. Leak surveys

Business districts are surveyed every year, unprotected steel areas every three years and all other areas every five years. Outside business districts the federal minimum is once every five calendar years at intervals not exceeding 63 months.

7. Submissions

Operators submit facilities-replacement documentation and work plans to the RRC by March 15, and each distribution operator submits a PHMSA annual report by March 15 for the preceding year. The 2026 RRC submission was made on March 11 and the 2025 PHMSA annual report on March 10.