



Recorded BEFORE change: Tripod 2026-09-09, PWM cap 3300, slew 250/s


Tracking diverges as the requested gait speeds up



The rate limiter delays correction, including reversal



Actual tracking does not follow the smooth target velocity



T-ratio decreases to the right (faster gait)