

Firmware Release Notes

Model Forge RT-12 | Revision 1.0

Overview

Release 3.2 adds bounded reconnect backoff and diagnostics for interrupted updates.

The signed image is compatible with hardware revisions B and C.

NOTICE: condition=upgrade starts; consequence=brief outage; avoidance=schedule maintenance

Upgrade procedure

- 1. Export the configuration.
- 2. Verify the image digest.
- 3. Apply the image and restart.

Change	Impact	Action
Reconnect backoff	Lower network load	None
Image format	Signed only	Verify digest