

Pressure Sensor Calibration

Model Nimbus PS-8 | Revision 1.0

Overview

The Nimbus PS-8 converts a sealed pressure input into a four-to-twenty milliamp signal.

Use a traceable reference and retain both as-found and as-left readings.

CAUTION: condition=port is pressurized; consequence=fluid release; avoidance=vent the port

Calibration task

1. Vent the process port.
2. Apply the zero reference.
3. Verify three span points.

Reference	Expected	Tolerance
0 percent	4.00 mA	+/-0.04 mA
100 percent	20.00 mA	+/-0.04 mA