





Rigid connection

*All rotational DOF transferred
→ artificial bending moments in model*



Pinned connection (internal hinge)

*R_y, R_z released at each member end
→ pure axial force transfer*