Labour Charges are capped at ₹299 per appliance

Semi Automatic WM - Power Unit

4.		4	
-71	м	g	
	v		

Description	Service Charge
Power 3 Pin Plug Top	₹200
Power Cord	₹500
Re wiring (Heavy damage)	₹650

Semi Automatic WM - Wash Issue



Description	Service Charge
Timer Wash (Electro Mechanical)	₹1050
Pulsator Snap	₹300
Thermostat	₹400
Pulsator with snap	₹850
Gear Box (With Pulley)	₹1550
Heater	₹950
Motor Pulley	₹600
Spin & Wash Capacitor	₹550
Wash Motor	₹1868
Wash Timer	₹750
V Belt	₹450

Labour Charges are capped at ₹299 per appliance

Spin Tub	₹900
Spin tub bellow	₹552
Timer Spin	₹781
Assembly Shocker 3 Qty	₹600
Spin Motor	₹1999
Coupler / Brake Wheel	₹400
Coupler Bush	₹150
Brake Shoe	₹200
Brake Plate	₹350
Lid Spring	₹150
Brake Wire	₹200

Semi Automatic WM - Water Leakage

Description	Service Charge
Drain Bellow	₹250
Drain Valve Assembly	₹500
Drain Valve Spring	₹50
Drain Case Cleaning	₹300

Semi Automatic WM - Accessories

Labour Charges are capped at ₹299 per appliance

Rat Mesh	₹400
Wash Lid	₹950
Back Cover	₹650
Drain Strip	₹100
Over Flow Pipe	₹220
Spin Cap	₹200
Outer Body / Cabinet	₹2600
Drain Selector	₹150
Drain Pipe	₹300
Lint / Magic filter	₹350
Knob	₹159
Inlet Pipe	₹200
Washing Machine Cover	₹600

Top Load WM - Power Unit

Description	Service Charge
Repair - Inverter PCB (Top Load)	₹2201
Power 3 Pin Plug Top	₹200
Power Cord	₹500
Wiring Kit	₹0
Replace (New) - Display PCB (Top Load)	₹0 ₹299 (Labour)

Labour Charges are capped at ₹299 per appliance

Repair - PCB (Top Load)	₹1677

Top Load WM - Wash Issue

Description	Service Charge
Capacitor	₹450
Motor Pulley	₹350
Pulsator Snap	₹342
Pressure sensor with pipe	₹950
Agitator	₹850
Outer tub	₹2200
Pulsator with snap	₹1059
Sensor Pipe	₹281
Drain Cleaining	₹300
Door Lock (Top Load)	₹1450
Brake Arm - (Whirlppol)	₹1200
AC Inlet Valve 1 way	₹750
AC Inlet Valve 2 way	₹970
AC Inlet valve 3/4 way	₹1400
DC Inlet Valve 1 way	₹999
DC Inlet Valve 2 way	₹1300
DC Inlet valve 3/4 way	₹2000

Labour Charges are capped at ₹299 per appliance

Direct Drive Motor	₹4000
Heater Sensor	₹500
Brake Arm - (Whirlppol)	₹1200
Heater	₹900
Door Lock (Top Load)	₹1450
Chuck Nut	₹250
V Belt	₹351

Top Load WM - Spin Issue

Description	Service Charge
Damper rod / Balancing Rods (4 Qty)	₹1400
Haier 6.5kg Clutch Assembly	₹3800 ₹299 (Labour)
Lid/Magnet Switch	₹530
Spin lid	₹700
Inner drum Plastic / Steel	₹2800
DC Drain Motor	₹1700
Clutch assembly	₹3500
Whirlpool - TSP (Complete Mechanism with hub)	₹4600
AC Drain Motor	₹1200

Labour Charges are capped at ₹299 per appliance

Drain Bellow	₹290	
Drain Valve Spring	₹150	
Drain Case Cleaning	₹400	

Top Load WM - Accessories

Description	Service Charge
Rat Mesh	₹400
Shocker Set - 3 Pieces	₹2400
Chemical Wash - Drum Dismantling & Assembling	₹1021
Inner Drain Hose	₹300
Outer Body / Cabinet	₹3000
Inner drum Plastic / Steel	₹2800
Stand/Trolley	₹1050
Descaling Powder	₹150
Extension Inlet Pipe 4Mtr (with adaptor)	₹750
Tub/Drain/Detergent-drawer Hose Rubber pipe	₹550
Sensor Pipe	₹250
Back Cover (Top Load)	₹650
Inlet Pipe / 1.5 Mtr with adaptor	₹650
Back Cover (Top Load)	₹650
Drain Pipe	₹300

Labour Charges are capped at ₹299 per appliance

Inlay Panel / Control Panel	₹650
Sensor Pipe	₹281
Pulsator with snap	₹1059
Pulsator Snap	₹342
Agitator	₹850
Power 3 Pin Plug Top	₹200
Outer tub	₹2200
Tap Adaptor	₹370
Motor Pulley	₹350
Knob	₹150
Washing Machine Cover	₹600
water filter	₹1400

Front Load WM - Power Unit



Description	Service Charge
Power 3 Pin Plug Top	₹250
Power Cord	₹500
Replace (New) - Display PCB (Front Load)	₹0 ₹299 (Labour)
Replace (New) - PCB (Front Load)	₹0 ₹299 (Labour)
LVT	₹800

Labour Charges are capped at ₹299 per appliance

Motor Control Unit(MCU)	₹1450	
Repair - Inverter PCB (Front Load)	₹3597	

Front Load WM - Wash Issue

Description	Service Charge
DC Inlet valve 3/4 way	₹2000
Door Lock (Front Load)	₹1450
Complete drum assembly (Bosch /Siemens)	₹9000
AC Inlet valve 3/4 way	₹1250
DC Inlet valve 3/4 way	₹2000
Gasket/ Door Diaphragm	₹1600
Complete Tub & Drum Assembly	₹6000
Front tub	₹2300
Back Tub (With bearings and seal)	₹3300
Capacitor	₹350
Pulley drive	₹750
Sensor Pipe	₹250
AC Inlet Valve 1 way	₹750
AC Inlet Valve 2 way	₹970
Pressure sensor with pipe	₹973
DC Inlet Valve 1 way	₹999

Labour Charges are capped at ₹299 per appliance

Direct Drive Motor	₹4000
Heater	₹900
Heater Sensor	₹500
Motor Universal	₹3300
V Belt	₹850
Drum Pulley	₹500

Front Load WM - Noise Issue

Description	Service Charge
Shocker Set - 3 Pieces	₹2400
Flange shaft Tri angle	₹2800
Drum Bearing/ oil Seal with Cleaning	₹2700
Shocker Set - 2 pieces	₹1600
Shocker Set - 3 Pieces	₹2400

Front Load WM - Spin Issue

Description	Service Charge
Drain Pump Motor	₹1350
Assembly Drain Pump	₹1600
Drain Pump Motor(Double way)	₹2200

Labour Charges are capped at ₹299 per appliance

Drain Rubber Hose	₹700

Front Load WM - Accessories

6.		
~	/	

Description	Service Charge
Chemical Wash - Drum Dismantling & Assembling	₹1200
Frontload Trolly (Stand)	₹1300
Rat Mesh	₹400
Door Hinge	₹1100
Descaling Powder	₹169
Outer body / Cabinet	₹3500
Dispenser Angle	₹450
Water Filter (Front Load)	₹1 ₹299 (Labour)
Extension Inlet Pipe 4Mtr (with adaptor)	₹750
Drain Rubber Hose	₹700
Drain Pipe	₹300
Inlet Pipe / 1.5 Mtr with adaptor	₹650
Knob	₹150
Noise Filter	₹550
Inlay Panel / Control Panel	₹850
Sensor Pipe	₹250

Labour Charges are capped at ₹299 per appliance

Back Tub (With bearings and seal)	₹3300
Tub/Drain/Detergent-drawer Hose Rubber pipe	₹550
Power Cord	₹500
Gasket/ Door Diaphragm	₹1600
Gasket Spring	₹250
Front holder/ Door lever	₹850
Back holder	₹750
Washing Machine Cover	₹800
Pulley drive	₹750
Outer Tub	₹2600
Door assembly	₹1800

Minor Repair

Description	Service Charge
Detergent Drawer Adjustment	₹0 ₹299 (Labour)
Electrical Plug Adjustment	₹0 ₹299 (Labour)
Drain Pipe Adjustment	₹0 ₹299 (Labour)
Filter cleaning	₹0 ₹299 (Labour)
Tap Adapter fixing	₹0 ₹299 (Labour)

Labour Charges are capped at ₹299 per appliance

iviacnine Level Aujustment	₹299 (Labour)
Cloth/Coin stuck	₹0 ₹299 (Labour)
Belt Adjustment	₹0 ₹299 (Labour)
Body Cabinet Adjustment	₹299

Installation

Description	Service Charge
Installation/Un-installation	₹100 ₹299 (Labour)

Descaling

Description	Service Charge
Descaling	₹200